

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):



- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

DRAWINGS :


1) SOFTWARE THAT SHOWS EA. MODEL THAT THE BUILDER OFFERS.



2) SOFTWARE THAT SHOWS STANDARD FEATURES (INSIDE + OUTSIDE) OF ALL MODELS




STANDARD SINGLE ENTRY DOOR




STANDARD WINDOWS IN LIVING RM

3) SOFTWARE THAT SHOWS OPTIONAL FEATURES (INSIDE + OUTSIDE) OF ALL MODELS




OPTIONAL ENTRY DOOR



OPTIONAL FIREPLACE, OPTIONAL WINDOWS

SOFTWARE THAT SHOWS FINAL SELECTIONS (INSIDE + OUTSIDE)

4)



STANDARD DOOR



OPTIONAL FIREPLACE, OPTIONAL WINDOWS

DRAWINGS:

5) SOFTWARE THAT SHOWS 'OPTIONAL FEATURES PRICES' + DESCRIPTIONS'

EXAMPLE:

- Fireplace in Living Room w/ WASHINGTON MANTEL — \$2700
- ~~3/4~~ DOUBLE ENTRY DOOR — \$300